

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**


**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**


**HURST-SON DESIGN CO.**  
Sam Hurst  
**18812 Maple Ht Blvd.**  
**Maple Ht Ohio 44137**  
**(216) 475-8376**  
E-mail smh129k yahoo.com















**HURST-SON DESIGN CO.**  
Sam Hurst  
18812 Maple Ht Blvd.  
Maple Ht Ohio 44137  
(216) 475-8376  
E-mail smht29k yahoo.com
















# Glass Block Window w/ Retractable Screen




HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376


# Glass Block Window w/ fixed Screen Attachment




HURSTSON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376





HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376



**HURST-SON DESIGN CO.**  
Sam Hurst  
18614 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376



HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376




② Operator  
Window  
rolls away from  
Assembly


PERSON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376

Hurst  
HES AT THE  
Bottom tier of  
the Glass block  
Section

③ The window  
section clear  
of window  
frame and  
remaining glass block  
window is pushed  
over




④a





connecting  
slots


④b  
Vent is attached  
To Glass block  
Section



⑤ Window with  
attached Vent  
is forced back  
into its  
cavity.




Window as it  
would appear  
from outside




HURST-SON DESIGN CO.  
Sam Hurst  
18812 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376


HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376



**HURST-SON DESIGN CO.**  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376




HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376




۲۹


To Be Used Where  
the (N-dimensional) Dimensions  
Constraints it uses.



Bogotá theft locks cable




Glare Block  
W,000) Assembly




**HURST-SON DESIGN CO.**  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376

↑ Offset track layers in each assembly is used to allow Glassblock Assembly the ability to pivot without

**Groove Cut Track**





**HURST-SON DESIGN CO.**  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376




**HURST-SON DESIGN CO.**  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376

HANDLE




Direction Locks  
Mechanism




Wood Flat  
→ Handled Pulldown  
Back

Wood Flat


→ Handled Pulldown  
Back




↔ motion




→ Handled Pulldown  
Back



Screen



Pull Handle  
Downward



HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376

HURST-SON DESIGN CO.  
Sam Hurst  
18612 Maple Hts Blvd  
Maple Hts, Ohio 44137  
(216) 475-8376

